

Need	Qty	Size inches	Description						
	2	9	ABDX 531629						(2 pc. Reflective)
	2	4	ABDX 531629						
	2	10	PLATE C						
	2	3	LD LMT						
			LT WT						
	2	3			219500	LB			
					66500	LB			
	2	3	NEW			LO			
	2	3	CAUTION:						
	2	2	OPEN TOP HATCH BEFORE						
			UNLOADING COMPARTMENT						
	8	2	CLOSE HOPPER GATES & ROOF						
			HATCHES BEFORE MOVING CAR						
	6	2	LOCK HATCH COVERS						
			BEFORE MOVING CAR						
	2	1.5	LEASED TO:						
	4	1.5			2	INCH HF COMP SHOES			
	2	1.5	1711	CU. FT.					
		4	A						
	2	1.5	1427	CU. FT.					
		4	AC						
	2	1.5	1427	CU. FT.					
		4	BC						
	2	1.5	1711	CU. FT.					
		4	B						
	1	1.5	DEFECT CARD						
	2	1	BLT	12/1998					(Consolidation Block)
	2	1.5	EXW	10-3	H	9-0			
			EW	8-6	H	14-4			
			CU. FT.	6270	CU. FT.				
	2	2				HEMPEL 35480			
					APPLIED	09/2007	BY	ABDX	
	2	1	PAINTED			09/2007			
			SHOP			ABDX			
			SYSTEM			56			
	2	1	RULE 88.B.2 INSP.						
			DATE						
			BY						(Due date no longer req'd)
	2	1	PROTECT INTERIOR COATING						
			WHEN ENTERING HOPPER						
			WEAR CLEAN RUBBER OVERSHOES						
			TOOLS MUST BE PROTECTED						
	2	1	CONSULT OWNER BEFORE						
			REPAIRING OR CLEANING HOPPER BODY						
	2	1	SERVICE		ABDX				
			EMERGENCY		ABDXL				
	2	1.5	CAUTION						
			NO SIDE						(Red Letters)
			LADDER						
	2	1	BRK.						
			CYL.						
			REL.						
	1	1	RET. VALVE						
	4	1	JACK HERE						
	2	1	JOB NO.	482					
	2	1.5	NOTE: THIS CAR HAS		4	COMPARTMENTS			
	3	6	A						
	2	6	AC						
	2	6	BC						
	3	6	B						
	2	1.5	36 INCH WHLS						
			SPRG D-5 7 OUTER - 6 INNER						
			GR-E COUPLERS, LOCKS,						
			SBE 60 CPLRS						